

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2019

Submitted Date:

03/27/2019

Document Number:

688401713**FIELD INSPECTION FORM**

Loc ID 318935 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 52060Name of Operator: M E III CORPORATIONAddress: 2670 PIERCE STCity: WHEAT RIDGE State: CO Zip: 80214**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
SCOTT ERNEST	303-233-2489	sernest1@hotmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242533	WELL	SI	08/01/2018	GW	123-10324	PERRY 3	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type			
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Call emergency numbe no answer it went to voice mail.

Corrective Action: Install sign to comply with Rule 210.d.

Date: 04/27/2019

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused unmarked 2" riser next to crude oil tank		
Corrective Action:	Comply with rule 603 f	Date:	04/27/2019
Type	OTHER		
Comment:	Stained soil around crude oil containment berm		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	04/27/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.025601,-104.843588
Comment:	No bullplugs on load lines on crude oil tanks				
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.				Date: 04/03/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Inadequate berms around tank(s)			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			
				Date: 04/27/2019

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	242533	Type:	WELL	API Number:	123-10324	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday March 27, 2019 at approximately 1055 hrs. I Randy Silver conducted an on-site inspection at a M E III corporation, site Perry #3 API #05-123-10324 in Weld County Colorado.</p> <p>While there, I observed a well site and production facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil: Rule 907 e Corrective action date of 4-27-19 See photos 4,5,6</p> <p>Inadequate berm around production tanks: Rule 605 a (4) Correction action date of 4-27-19 See photos 3,4,6,10</p> <p>Crude oil load line bull plug: Rule 604 c (2) o Corrective action date of 4-3-19 See photos 6,7,8,9</p> <p>Emergency contact number: Rule 210d Corrective action date of 4-27-19 See photo 1</p> <p>Unused, unmarked riser: Rule 603 f Corrective action date of 4-27-19 See photo 8</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	03/27/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401987361	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775642
688401714	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775636