

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2019

Submitted Date:

03/27/2019

Document Number:

688800483**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Kirschner, Steven		steven.kirschner@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458834	SPILL OR RELEASE	AC	02/21/2019		-	Thomas Jacquez E1 PW Line	EI

General Comment:

On March 26, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP Thomas Jacquez E #1 PW Line Spill/Release Point ID #458834. This field inspection was performed to verify if REM #12660 had been completed.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Oily residue was observed at the Citizen's Animas Ditch head gate structure near the inlet to the High Flume siphon. Ponded water at both ends of the siphon contained E and P waste. Impacted material and vegetation was observed along the High Flume siphon bypass.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 03/28/2019

Reportable: YES

GPS: Lat 37.103723

Long -107.897424

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
<p>On March 26, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP Thomas Jacquez E #1 PW Line Spill/Release Point ID #458834. This field inspection was performed to verify if REM #12660 had been completed. COGCC staff met with a landowner whose property was impacted by the release.</p> <p>Oily residue was observed at the Citizen's Animas Ditch head gate structure near the inlet to the High Flume siphon. Ponded water at both ends of the siphon contained E and P waste. Impacted material and vegetation was observed along the High Flume siphon bypass.</p> <p>A follow up meeting with the landowner and a BP representative on 3/27/2019 delineated further actions required.</p> <p>The head gate structure at the High Flume siphon inlet shall be cleaned of all residue from Spill/Release Point ID #458834. The pooled water at the siphon inlet shall be removed with a vac truck. The remaining fluid in the siphon shall then be evacuated from the siphon outlet. Fluid volume removed and final disposition information shall be provided to COGCC Environmental staff, upon completion.</p> <p>Stained soil and vegetation shall be removed from the High Flume siphon bypass. Representative confirmation samples shall be collected to ensure compliance with Table 910-1. Samples shall be analyzed for any/all analytes that were above detection limits in the most recent sampling event.</p> <p>As stated previously as a condition of approval for Supplemental Form 27 Document #401973458, BP shall have equipment/personnel deployed when water is returned to the ditch system.</p>	hughesjo	03/27/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401987102	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775310
688800484	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775308