

Construction and Stormwater Inspection

April 2, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 455456

Inspection Document #: 682404758

Weld County, CO

NWNE Section 18 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EAST AULT 18-C PAD
Location ID: 455456



Photo 1. Photo taken from the eastern location, facing South. Photo illustrates a ditch and berm BMP, and the fill slope has been tracked.



Photo 2. Photo taken from the eastern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: EAST AULT 18-C PAD
Location ID: 455456



Photo 3. Photo taken from the eastern topsoil stockpile on April 2, 2019, facing West. Operator has failed to stabilize the south-facing topsoil stockpile side since the previous inspection on 3/12/19. Also, leaving the stockpile steep like this would make it difficult to manage weed establishment.



Photo 4. Photo taken from the western topsoil stockpile on March 12, 2019, facing East. See comments under Photo 3.

Inspection Photos
Location Name: EAST AULT 18-C PAD
Location ID: 455456



Photo 5. Photo taken from the north-facing topsoil stockpile side on April 2, 2019, facing South. Operator has only stabilized the north-facing side and not the south-facing side.