

Inspection Photos  
Location Name: Open Range 18  
Location ID: 447512



**Photo 1. Overview of location taken at entrance facing east.**



**Photo 2. Example of debris, pile of oily used secondary containment devices.**

Inspection Photos  
Location Name: Open Range 18  
Location ID: 447512



**Photo 3. Example of poor housekeeping, piles of stained soil where large volume storage tank sat during frack operations.**



**Photo 4. No liner apparent under tank being installed.**



Inspection Photos  
Location Name: Open Range 18  
Location ID: 447512



Photo 5. Example of poor housekeeping, oily fluid in secondary containments.



Photo 6. Close-up of Photo 5 to show hoses coming out of containment vessels.

Inspection Photos  
Location Name: Open Range 18  
Location ID: 447512



**Photo 7. Example of poor housekeeping, overturned secondary containment stock tank, stained soil, trash/debris.**



**Photo 8. Close-up of Photo 7 to show stained soil.**



Inspection Photos  
Location Name: Open Range 18  
Location ID: 447512



**Photo 9. Frack tanks stored with incomplete secondary containment.**



**Photo 10. Example of poor housekeeping, overturned chemical tote.**

Inspection Photos  
Location Name: Open Range 18  
Location ID: 447512



**Photo 11. . Example of poor housekeeping, hoses stored without containment.**



**Photo 12. Example of poor housekeeping, hoses stored without containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 689802440