

# Inspection Photos

API: 05-071-06340

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/2/2019

## Inspection Photos



**Photo 1.** There is an erosion channel that developed at the southeast side of the location along the access road.



## Inspection Photos



**Photo 2.** There is signs of sediment deposition on the pad. A ditch at the base of the cut slope may be needed to retain sediment.

## Inspection Photos



**Photo 3.** Facing toward the location.