

Inspection Photos

API: 05-071-06339

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/2/2019

Inspection Photos



Photo 1. Facing toward the wellhead. It appears there was leakage.

Inspection Photos



Photo 2. There is stained soil near the engine skid.

Inspection Photos



Photo 3. Past the location on the main road in the canyon there are signs of vehicle rutting and erosion.