

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2019

Submitted Date:

04/03/2019

Document Number:

685305798

**FIELD INSPECTION FORM**

Loc ID 335737 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 90615  
Name of Operator: TUDEX PETROLEUM INC  
Address: 2121 39TH AVE NE UNIT E  
City: CALGARY State: AL Zip: T2E 6R7

**Findings:**

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203258	WELL	PR	08/01/2014	OW	001-08767	HI-LAND 10-B	TA
203259	WELL	PR	05/01/2015	OW	001-08768	HI-LAND 10-G	TA

**General Comment:**

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment decommissioning and removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access off paved road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Other	Separator	<= 1 bbl	
Comment:	Fluid mixture of produced water and crude oil from inside separator vessel released when drain valve hung on concrete cribbing and broke off.		
Corrective Action:	Clean up was done immediately with fluids cleaned up and impacted soil and gravel shoveled up and placed on plastic liner for haul off. Valve was reinstalled on separator vessel.		Date: <u>04/01/2019</u>
In Containment: No			
Comment:	Release was immediately contained and cleaned up.		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chain link fencing.		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Bird Protectors	# 2		
Comment:	Separator heater stacks.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Electrical service equipment.		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Production equipment building. Started tear down on building. Metal siding and wooden underlayment removed. Metal roof removed.		
Corrective Action:			Date:

Type: Deadman # & Marked	# 5	
Comment:	Located (5) marked anchors.	
Corrective Action:		Date:
Type: Other	# 2	
Comment:	Concrete pumping unit bases.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:	Removed 1 from inside production equipment building the other is still inside the framed walls of production equipment building.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,
Comment:	Fluids in tank.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	Fluids in tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203258 Type: WELL API Number: 001-08767 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is an Orphaned Well Program well. Valves closed at wellhead. Equipment decommissioning, removal and salvage is in progress.

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 203259 Type: WELL API Number: 001-08768 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is an Orphaned Well Program well. Valves closed at wellhead. Equipment decommissioning, removal and salvage is in progress.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>The equipment decommissioning, removal and salvage task is continuing with the Tudex Petroleum Inc. moving to the Hi-Land site. The Hi-Land site is comprised of (2) production tanks and (1) produced water tank and a Production equipment building with (2) horizontal separators. The (2) wells serviced by the production facility are visible to the W of production facility with pump jacks attached to the rod string.</p> <p>Initial focus is the tear down of the production equipment building with the metal siding and wood underlayment removed and building stripped to the framing. The metal roof was removed.</p> <p>There are (2) horizontal separators inside the building. The heater stack was removed and laid down and the W separator was removed from the building.</p> <p>Spill/Release - During the removal the vessel drain line and valve hung on the concrete cribbing breaking the line off and releasing approximately (1) BBL of mixture containing produced water and crude oil. The release was immediately contained and fluids cleaned up. The impacted soil was shoveled up and placed on plastic liner for haul off.</p> <p>Site was secured and caution tape ran before shut down and departure for the day</p>	stjohnw	04/01/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305805	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783327">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783327</a>