

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2019

Submitted Date:

04/03/2019

Document Number:

688800495

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325168 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87415

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.
Fischer, Alex		alex.fischer@state.co.us	
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105402	PIT	AC			-	IGNACIO 33-8 2	EI
214188	WELL	PR	01/01/1995	GW	067-05508	IGNACIO 33-8 2	EI

General Comment:

On March 27, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Logos Operating LLC Ignacio 33-8 #2. For the most recent field inspection report of this facility, please refer to document #688800339. This site visit was to determine the progress on REM Project #7297.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign mounted to meter run shack.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Orange safety fencing was being installed around the excavation during this inspection.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gathering Line	# 1		
Comment:	Williams Field Services gathering line riser near SW corner of location.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 105402 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 214188 Type: WELL API Number: 067-05508 Status: PR Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Please refer to Remediation Project #7297 (Form 27 Document #2230472) for more information regarding this project. Prior to this inspection, the area where Pit Facility ID #105402 had been, was excavated and impacted material was hauled off for disposal. Confirmation samples had reportedly been collected and sent off for analysis.

Corrective Action: The operator shall supply waste disposal manifests on a supplemental Form 27.

Date: 05/31/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 105402 Lat: 37.129317 Long: -107.671254

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Historical pit associated with Ignacio 33-8 #2 (API #067-05508).

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
<p>On March 27, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Logos Operating LLC Ignacio 33-8 #2. For the most recent field inspection report of this facility, please refer to document #688800339. This site visit was to determine the progress on REM Project #7297.</p> <p>Please refer to Remediation Project #7297 (Form 27 Document #2230472) for more information regarding this project. Prior to this inspection, the area where Pit Facility ID #105402 had been, was excavated and impacted material was hauled off for disposal. Confirmation samples had reportedly been collected and sent off for analysis. Kelly Oilfield Services personnel were installing orange safety fencing around the excavation during this inspection.</p> <p>The operator shall supply waste disposal manifests on a supplemental Form 27.</p>	hughesjo	04/03/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800496	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783443