

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2019

Submitted Date:

04/04/2019

Document Number:

675002120

FIELD INSPECTION FORM
 Loc ID 312612 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|-----------------|
| Ried, Jordan | 970-563-400 | maralextechjr@gmail.com | All Inspections |
| Colby, Lou | | lou.colby@state.co.us | |
| Graves, Jim | | mrinc20@qwestoffice.net | |
| Hartman, Robert | 970-244-3041 | bhartman@blm.gov | All Inspections |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 222020 | WELL | PA | 10/16/2017 | GW | 077-08622 | SOUTH SHALE RIDGE 10-15 | PA |

General Comment:

This is a follow up inspection from Doc#675001770 dated 1/16/19 . Required Corrective Action (s) items noted in previous inspections have not been satisfied, but have time remaining to meet corrective action date of 4/16/19

This well is included in the Administrative Order of Consent No. 1V-609.

Well was plugged on 10/16/17 . Form 6 (S) Doc#401554007 in process. Well surface evidence of well at time of inspection.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: No Emergency contact information or signage of any kind on location at present time

Corrective Action: Install sign to comply with Rule 210.b.

Date: 05/03/2019

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Pipeline and riser left on location
Items remain on location from previous inspection #675001770 dated 1/16/19
(see photos 2-7)

Corrective Action: Comply with Rule 603.f .

Date: 04/16/2019

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 222020 Type: WELL API Number: 077-08622 Status: PA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well was plugged on 10/16/17 . Form 6 (S) Doc#401554007 in process. Well surface evidine of well at time of inspection.Corrective Action:

Date: _____

WorkoverComment: Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Stormwater erosion not being controlled on the location at this time.
Heavy erosion and movement of sediment from North and east hillsides onto location. .
Sediment erodes across the location then moving off location on the west side and along both entrances onto and across access road then down the ravine. (See Photos 8-15)

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/03/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 675002121 | Inspection 675002120 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783917 |