

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2019

Submitted Date:

04/04/2019

Document Number:

674301900

**FIELD INSPECTION FORM**

Loc ID 318000 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		dnr_cogccenforcement@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240356	WELL	PR	07/01/2017	OW	123-08144	MORGAN 'A' 2	SI

**General Comment:**



**Inspected Facilities**

Facility ID: 240356 Type: WELL API Number: 123-08144 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>On 2/22/2019; I received a complaint #200446986 in regard to public safety around the wellhead, pump jack and electrical equipment. I, Tom Peterson, COGCC field inspector, performed an inspection of the facility at approximately 12:30 PM on 2/22/2019. The complainant states witnessing children playing around the equipment. The current fencing on location consists of pipe fencing partially covering the pump jack weights and no fencing around the wellhead or electrical equipment. See attached photos.</p> <p>Rule violations found during the inspection are: Rule 605. c. (3) with a corrective action date of 3/29/2019, Rule 210. b. with a corrective action date of 3/29/2019.</p> <p>KPK Morgan A2, location ID 318000.</p> <p>Original inspection was performed on 2/22/2019 in response to complaint# 200446986</p> <p>On 4/4/2019, I Tom Peterson, along with supervisor Adam Kraich, performed a follow up inspection to document #674301660 at approximately 10:00 hrs. The prior inspection document identified three corrective actions.</p> <ol style="list-style-type: none"> <li>1. Well signage is faded and illegible, citing rule 210.b</li> <li>2. Well signage is missing emergency contact information, citing 210.b</li> <li>3. Equipment at wellhead, pumping unit and prime mover are unsecured, and sit in the middle of a developed neighborhood. Citing 605.c</li> </ol> <p>The Corrective action time frames assigned to these corrective actions expired 3/29/2019. Follow up inspection performed on 4/4/2019 observed none of the corrective actions have been addressed.</p> <p>See photos for detail.</p>	<p>petersont</p>	<p>04/04/2019</p>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674301901	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4784134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4784134</a>