

Inspection Photos

Location: 447512 pen Range 18 Pad

Peters 0781 wells.

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 1- Overview of location

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 2- Trash Can



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 3-Welding shack, weed burner.

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 4- Hoses stored in stormwater.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 5-



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 6-puddled stormwater, stock tank is in photo #7



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 7- Overturned stock tank, stained soil. Spilled fluid and soil should be removed in 48 hrs (per COGCC Corrective Action matrix) and handled per COGCC rule 907. Note combustor in background. Photo is taken looking north, on the North east corner of pad.

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 8- Fluid stored in flat tanks and stained soil. Fluid and soil should immediately be removed and handled per COGCC rule 907.

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 9- Frack tanks stored with incomplete secondary containment. COGCC rule 605.G should be complied with when tanks are in use

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 10- AGT being installed, see photo #11 for close up



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location: 447512 pen Range 18 Pad
Peters 0781 wells.
Inspection Date: 3/27/19
Photos taken by Emily Waldron

Photo 11- AGT being installed. Is COGCC rule 605.a(4) met with this install? Specifically, is there a synthetic or engineered liner placed directly beneath the tank?



Inspection Photos
Location: 447512 pen Range 18 Pad
Peters 0781 wells.
Inspection Date: 3/27/19
Photos taken by Emily Waldron

Photo 12- Overview of location taken at entrance facing east. Stained soil stockpiled were observed, soil should immediately be removed and handled per COGCC rule 907.

Inspection Photos

**Location: 447512 pen Range 18 Pad
Peters 0781 wells.**

Inspection Date: 3/27/19

Photos taken by Emily Waldron



Photo 13- Stored liner material, liner should be removed in 48 hrs (per COGCC Corrective Action matrix) and handled per COGCC rule 907.A.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources