

**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Valve set where spill/release occurred.**



**Valve locked out.**



**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Dirt berms constructed in an attempt to contain fluids.**



**Flow path towards irrigation ditch and ultimately freshwater emergent wetland.**



**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Ditch approximately 35' to the west of the valve set.**



**Water course that release reportedly followed.**



Inspection Photos  
Location Name: Leroy McCaw B #1  
API: 05-067-07009



View of freshwater emergent wetland from southeastern corner of Leroy McCaw B #1 location.



Capacity is not labeled on produced water sign.

**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Notice of domestic tap posted on vertical heated separator.**



**Domestic tap and valve can on western edge of location.**



**Inspection Photos**  
**Location Name: Leroy McCaw B #1**  
**API: 05-067-07009**



**Leroy McCaw B #1 pump jack.**



**Lube oil container on secondary containment.**