

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2019

Submitted Date:

04/04/2019

Document Number:

687904492**FIELD INSPECTION FORM**
 Loc ID 333605 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Roland, Kandis		kroland@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214835	WELL	PR	06/01/2012	GW	067-06439	MCCULLOGH 1	PR

**General Comment:**

Conducted on site inspection of location as required.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two-track dirt road for a couple miles to location.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Framed metal sign posted at wellhead and at separator.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (505) 324-5170

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:	10 on produced water tanks, 1 on separator stack.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with bradenhead access.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	10	500 BBLS	HEATED STEEL AST		,	
Comment:	Tank battery is large with proper placards on each tank. A pumping unit also sits in a metal building to transfer Produced water.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Secondary containment is large with tall berms of clay and screened rock around entire perimeter.				
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 214835	Type: WELL	API Number: 067-06439	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Pass	Ditches	Pass			
Slope Roughening	Pass					
Rip Rap	In Process					
Waddles	In Process					
Seeding	Pass					
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass					

Comment: Northern edge of location has had slope roughening and seeding last summer/fall. Northern edge of location also has rip rap and waddles installed that appear to be functioning as designed. Southern edge of location has waddles and rip rap installed on offsite drainage areas and they appear to be working as designed. Southeastern corner of location appears to have a washout from location during the winter melt down, and needs some attention.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT