

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2019

Submitted Date:

04/05/2019

Document Number:

690003254

FIELD INSPECTION FORM

Loc ID 302455 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10604
 Name of Operator: COMPLETE ENERGY SERVICES INC
 Address: 4727 GAILLARDIA PKWY STE 250
 City: OKLAHOMA CITY State: OK Zip: 73142

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Sellmer, Travis	(720) 606-1906	tsellmer@hpdswd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159270	UIC DISPOSAL	AC	04/27/2009		-	HPD PLATTEVILLE 1	AO
298847	WELL	IJ	04/12/2012	DSPW	123-29168	HPD PLATTEVILLE 1	AC

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Facility Entrance from County Rd		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Shack		
Corrective Action:		Date:	

Equipment:

Type	#	Capacity	Type	Tank ID	SE GPS	corrective date
Prime Mover	# 1					
Comment:	750 HP					
Corrective Action:					Date:	
Prime Mover	# 1					
Comment:	500 HP					
Corrective Action:					Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	1000 GAL	STEEL AST		40.216921,-104.719660
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 159270 Type: UIC API Number: - Status: AC Insp. Status: AO

Facility ID: 298847 Type: WELL API Number: 123-29168 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 1362 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: ACGMI

TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 06/13/2014

Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTReq: _____

Comment: Max Allowable Pressure: 1427

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>On Friday, April 5, 2019 at 11:06, I, Craig Carlile conducted an on-site inspection at: 302455, HPD PLATTEVILLE-63N66W 24NENE Operated by: High Plains Disposal While there I observed: Injection Well and related facilities Routine UIC inspection. I spoke with: Travis Sellmer, discussed the date for the next required MIT as no later than: May 28, 2019 This is a summary of the inspection report.</p>	carlilec	04/05/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003255	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4786357