

Inspection Photos

Loc#335553

Operator: Ursa

Inspection Number: 692400826

Inspection Date: 3/25/2019





Photo#1:
NW corner of Pad where Stormwater has collected & blown out channels through Fill slope.

March 25,2019



Photo#2:
NW corner of Pad where Stormwater has collected & blown out channels through Fill slope.



Photo#3:
Point where stormwater discharges on outside of
NW Fill slope.

March 25,2019



Photo#4:
Point where stormwater discharges on outside of
NW Fill slope.



Photo#5:
View over fill slope to West. Areas of fill slopes are in need of stabilization.

March 25,2019



Photo#6:
View over fill slope to East. Areas of fill slopes are in need of stabilization.





Photo#7:
East side of Pad where Stormwater has collected & blown out channels through Fill slope.

March 25,2019



Photo#8:
Point where stormwater discharges on outside of East Fill slope.



Photo#9:
Base of East fill slope showing Sediment migration.

March 25,2019

Photo#10:
Calf carcasses have been dumped on Northeast
area of Fill slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley Farms I Pad Loc#335553