



Photo 1 –Posted Sign on at land farm.



Photo 2 –Gate was open at time of inspection. Snow melt at entry, this snow melt appears to be outside of the secondary containment of the treatment area.



Photo 3 –trash at gate.



Photo 4 –Eastern cell. Some liquid hydrocarbon present in snowmelt



Photo 5 –Land treatment area.



Photo 6 –Land treatment area. Looking west



Photo 7 –wildlife scat.



Photo 8 –Land treatment area. Pooling stormwater.



Photo 9 –wildlife scat.



Photo 10 –Looking west at western most cell of land treatment area. It appears that the facility drains to the west, note pooling.



Photo 11 –land treatment area.



Photo 12 –Western land treatment cell



Photo 13 –Western most containment of land treatment area



Photo 14 –Fence of land treatment area



Photo 15 –North side of secondary containment area. Corrective Action: assure that secondary containment is being maintained.



Photo 16 Drive over secondary containment at access to land treatment location.



Photo 17 –Pooled water inside land treatment area. Some water had liquid hydrocarbon.



Photo 18 –land treatment area secondary containment.



Photo 19 –Land treatment area.



04.05.2019 11:01

Photo 20 –Land treatment area.

