

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2019

Submitted Date:

04/08/2019

Document Number:

687904515

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
311909 _____ Stewart, Joseph _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		inspections@catamountep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216324	WELL	PR	08/26/1993	GW	067-07930	HARMON GAS UNIT A 2	PR
435727	WELL	PR	08/12/2017	GW	067-09901	IGE 141	PR

General Comment:

This is an onsite inspection of the location as required. [Downloadable photos at the end of this inspection report.](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel access road through locked gate.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign is posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information is posted.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	TRASH		
Comment:	Secondary containment has tires in it.		
Corrective Action:	Tires are trash. Comply with Rule 603.f.	Date:	04/18/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2	
Comment:	Wellhead with PVC bradenhead access.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment of IGE 141 produced water tank has multiple tears in liner on base and on walls.			
Corrective Action:	Repair or replace secondary containment liner to comply with Rule 906.d.(1)			Date: 05/08/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
	Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 216324 Type: WELL API Number: 067-07930 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 435727 Type: WELL API Number: 067-09901 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention under oil day tanks ofr engines.
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904516	Location overview	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788224
687904517	Tires in secondary containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788225
687904518	Liner failure northwest corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788226
687904519	Liner base failure northwest corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788227
687904520	Liner failure southeast corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788228
687904521	Liner failure along northern wall	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788229