

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2019

Submitted Date:

04/08/2019

Document Number:

687904511

FIELD INSPECTION FORM

Loc ID 311897 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216577	WELL	PR	04/08/2011	GW	067-08183	FASSETT 1-A	PR
276638	WELL	PR	11/20/2005	GW	067-09025	IGW 104	PR
290037	WELL	PR	06/09/2009	GW	067-09347	IGW 120	PR

General Comment:

[Inspected location as required.](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through locked gate.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels posted.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Posted signs at each wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pump Jack	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Wellheads with PVC bradenhead access.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	2" steel flowline from Fassett 1A to seperator.		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	2" steel flowline from Fassett 1A separator to meter house and to dogleg.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		

Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	2" Steel flowlines from separator to gas engine fuel gas on IGW 120 and IGW 104		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	3" steel flowlines from IGW 120 and IGW 104 wellheads to respective separators.		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:	On separator stacks.		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	3" steel flowline from IGW 120 and IGW 104 separators to dogleg.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		
Comment:	Top has expanded metal screen across the top.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>216577</u>	Type:	<u>WELL</u>	API Number:	<u>067-08183</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing.</u>								
Corrective Action:								Date:	
Facility ID:	<u>276638</u>	Type:	<u>WELL</u>	API Number:	<u>067-09025</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing.</u>								
Corrective Action:								Date:	
Facility ID:	<u>290037</u>	Type:	<u>WELL</u>	API Number:	<u>067-09347</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing.</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904512	Location overview	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788222