

FORM
22

Rev
06/18

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:
04/08/2019

Accident Tracking No.:
401989924

ACCIDENT REPORT

As required by Rule 602.d.

CONTACT INFORMATION

☒ Initial Notice of Accident ☐ Subsequent Notice of Accident

OGCC Operator Number: 10503 Contact Name: Teresa Jackson
Name of Operator: RED HAWK PETROLEUM LLC Phone: (479) 2446543
Address: 1250 WOOD BRANCH PARK STE 400 Fax: ()
City: HOUSTON State: TX Zip: 77079 Email: tjackson@atex-energy.com

ACCIDENT DATE, TIME, and LOCATION (Please be as specific as possible)

Date of Accident: 03/06/2019 Time of Accident: 2:00 AM
API Number: 05- Facility ID: 424744 Type of Facility: LOCATION
Well/Facility Name: Staudinger Well/Facility Num: 1-31H
County: WELD
Location: QTRQTR: NENE Sec: 31 Twp: 8N Rng: 61W Meridian: 6
Lat: 40.624394 Long: -104.242448
Field Name: DJ HORIZONTAL NIOBRARA Field Number: 16950

Was there a reportable E & P waste spill or release associated with this accident? Yes ☒ No ☐
If YES, enter the Document Number of the Initial Spill/Release Report, Form 19: 401985507
Was there a Grade 1 Gas Leak associated with this accident? Yes ☐ No ☒
If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report, Form 44: _____

DESCRIPTION OF ACCIDENT

Number of members of the general public injured: 0
Number of workers injured: 0
Number of general public fatalities: 0
Number of worker fatalities: 0

Type of Accident (check all that apply):

☒ Fire
☐ Explosion
☐ Detonation
☐ Uncontrolled Release
☐ Other Description: _____

Detailed Description of Accident:

- Do not include names of injured, injuries, or medical treatment information.
- Subsequent Report must include Root Cause.

The Briggsdale fire department notified Luke Crumley (pumper for Redhawk) of a fire at the Staudinger facility. Another pumper in the area had already gone in and shut the well in. They quickly extinguished the fire and Mr. Crumley arrived at the location early the next morning to begin inspecting the facility and noted the facility was a total loss. During the inspection Mr. Crumley identified what he believes to be the source of the fire. It appears to be the heater treater fire tube had a leak which caused the fire. After discussions with the Houston management he found out the heater treater was approximately 5 years old so discussions with the manufacturer will take place during the RCA to determine if this is a manufacturer's defect as opposed to a simple leak of the heater treater. Remediation started immediately. Weld Labs is handling the soil sampling for so further removal of soil and remediation can be completed.

OTHER NOTIFICATIONS

List all parties and agencies that were notified or responded to the accident. (For example: Local Government Designee, Municipality, County, BLM, EPA, CDOT, Local Emergency Planning Coordinator, etc.)

Date	Agency	Contact	Response

OPERATOR COMMENTS and SUBMITTAL

--

This form must be signed by an authorized agent of the entity making assertion.

I certify under penalty of perjury that this report has been examined by me and to the best of my knowledge is true, correct and complete.

Print Name: Teresa Jackson

Email: tjackson@atex-energy.com

Signature: _____

Title: Regulatory Manager

Date: 04/08/2019

CONDITIONS OF APPROVAL, IF ANY:**COA Type****Description**

	Prior to 6/30/2019 provide subsequent Form 22 with root cause. Include documentation of policies, procedures, practices and training implemented to prevent future occurrences.
--	---

Attachment Check List**Att Doc Num****Name**

--	--

Total Attach: 0 Files

<u>General Comments</u>		
<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval
Total: 0 comment(s)		

]