

**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**





**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**Sediment build up in ditch around cut slope.**



**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**Berm washed out behind separators.**



**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**Sediment over flow by the tank battery.**

**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**Sediment build up in ditch around cut slope.**



**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**Dirt stock piles.**

**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**Erosion from culvert outlet flow.**



**GM 44-1**  
**Api. # 05-045-07448**  
**Inspection # 689702998**



**Checkdam is washed out and needs maintained.**