

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2019

Submitted Date:

04/09/2019

Document Number:

695100451**FIELD INSPECTION FORM**
 Loc ID 309270 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	<a href="#">All Inspections</a>
Mack, Ronald		ronaldmack@tcenergy.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290929	WELL	PR	01/11/2008	GW	071-09320	APACHE CANYON 35-07	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	IMPACTED SOIL AROUND WELLHEAD A CHALKY RUST COLLARD IMPACTION TO THE LEFT OF WELLHEAD AND AN OILY IMPACTION TO THE RIGHT (WEST) OF WELLHEAD. DRIVEHEAD IS NOT RUNNING AT TIME OF INSPECTION.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/09/2019
Type	UNUSED EQUIPMENT		
Comment:	UNUSED EQUIPMENT STORED ON LOCATION NEAR METER HOUSE. (2" POLLEY PIPE AND APPEARS TO BE SOME TELEMTRY EQUIPMENT).		
Corrective Action:	Comply with Rule 603.f .	Date:	05/09/2019
Type	OTHER		
Comment:	ENGINE SKID HAS ROUGHLY 1 TO 1.5" OF OIL. IMPACTED SOIL ON SOUTH SIDE OF ENGINE SKID. IMPACTED SOIL TO NORTH OF SKID AND ALONG HYDRAULIC HOSES LEADING FROM SKID TO WELLHEAD MORE IMPACTED SOIL ON NORTH SIDE OF SKID AND ON THE WEST SIDE OF SKID.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B	Date:	05/09/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	TELEMTRY EQUIPMENT		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 290929 Type: WELL API Number: 071-09320 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100452	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789644">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789644</a>