

Inspection Photos
Location Name: GE #30-3
Location ID: 309291



Photo 1 Storm water: Reels on road to location allowing sediment into water way



Photo 2 sediment in water way from road in Photo 1

Inspection Photos
Location Name: GE #30-3
Location ID: 309291



Photo 3 Storm water: Reels on road to location allowing sediment into water way



Photo 4 sediment from road being carried of road way into water way.

Inspection Photos
Location Name: GE #30-3
Location ID: 309291



Photo 5 Culvert at entrance to location plugged allowing storm water and sediment to flow across access road in to water way.



Photo 6 Meter/ Sep house

Inspection Photos
Location Name: GE #30-3
Location ID: 309291



Photo 7 WH. **Well is TA**



Photo 8 Unused equipment: unused unmarked not LOTO 2" piping and 1" electric lines

Inspection Photos
Location Name: GE #30-3
Location ID: 309291



Photo 9 Fence around pit in disrepair



Photo 10 storm water: pit appears to have sediment and growth in liner.

Inspection Photos
Location Name: GE #30-3
Location ID: 309291



Photo 11 Unmarked Guy line anchor