

Inspection Photos
Location Name: New Elk 24-16
Location ID: 309390



Photo 1 WH



Photo 2 loc pic

Inspection Photos
Location Name: New Elk 24-16
Location ID: 309390



Photo 3 meter/sep building

Photo 4 Pit

Inspection Photos
Location Name: New Elk 24-16
Location ID: 309390



Photo 5 Stained soil around HYD skid

Photo 6 Stained soil around HYD skid

Inspection Photos
Location Name: New Elk 24-16
Location ID: 309390



Photo 7 Guy line anchor not properly marked

Photo 8 Guy line anchor marker missing