

**Inspection Photos**  
**Location Name: New Elk #26-12**  
**Location ID: 308662**



**Photo 1 Sep/meter run house**



**Photo 2 loc pic**



**Inspection Photos**  
**Location Name: New Elk #26-12**  
**Location ID: 308662**



**Photo 3 Stained soil inside cellar of WH**



**Photo 4 Stained soil around HYD skid**



**Inspection Photos**  
**Location Name: New Elk #26-12**  
**Location ID: 308662**



**Photo 5 stained soil around HYD skid**



**Photo 6 Stained soil around liquid ring skid**



**Inspection Photos**  
**Location Name: New Elk #26-12**  
**Location ID: 308662**



**Photo 7 storm water erosion from back of location making large reel into produced water pit**



**Photo 8 Storm water no berm around back side of production pit**



**Inspection Photos**  
**Location Name: New Elk #26-12**  
**Location ID: 308662**



**Photo 9 Loc pic**



**Photo 10 loc pic**



**Inspection Photos**  
**Location Name: New Elk #26-12**  
**Location ID: 308662**



**Photo 11 Thief hatch open**



**Photo 12 Unused equipment: guard and red tee handle**