

Inspection Photos

4/09/2019

Operator: DENVER EAST MACHINERY COMPANY
- 24040

Location ID: 390528

Inspection Doc. Number: 682504713
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 1: Photo taken from the southeast corner of the location, facing west. Previous inspections documented that reclamation does not appear to be progressing and required operator to perform additional reclamation activities by 3/31/2018. Photo shows no additional reclamation or remediation activities appear to have been conducted. The location/disturbance remains predominantly bare and exposed soil, or undesirable weedy plant species.



Photo 2: Photo taken from the southeast corner of the location, facing northwest. See comments under photo 1.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 3: Photo taken from the southeast corner of the location, facing north. See comments under photo 1.



Photo 4: Photo taken from the disturbance area, facing west. Photo shows stormwater erosion degradation on location.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 5: See comments under photo 1.



Photo 6: See comments under photo 1.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 7: Photo taken from the northwest area of the location, facing north. See comments under photo 1.



Photo 8: Photo taken from the northwest area of the location, facing west. Photo shows erosion degradation on location.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 9: Photo taken from the northwest end of the location. Photo shows wattles are not longer in proper functioning condition.



Photo 10: Photo taken from the northwest area of the location, facing east. Photo shows erosion degradation on location.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 11: Photo taken from the north end of the location. Photo shows stormwater berm has been blown out and no longer in proper functioning condition. Photo also shows erosion degradation on location.



Photo 12: Photo taken from the northeast end of the location, facing northeast. Photo shows silt fence is no longer in proper functioning condition.

Inspection Photos
Operator: DENVER EAST MACHINERY COMPANY - 24040
Location ID: 390528



Photo 13: Photo taken from the northeast end of the location, facing southeast. Photo shows silt fence is no longer in proper functioning condition.



Photo 14: Photo taken from the west end of the location. Photo shows erosion degradation on the location.