

Inspection Photos

API: 05-055-06137

Operator: SILVER MOUNTAIN PRESERVE

Inspection Date: 4/4/2019

Inspection Photos



Photo 1. Facing north at the location. The location is bare of vegetation. It appears some vegetation has been burned off but vegetation has not re-established.

Inspection Photos



Photo 2. Facing south at the location. The location is bare of vegetation. It appears some vegetation has been burned off but vegetation has not re-established.

Inspection Photos



Photo 3. Close up view of the ground. There is some burnt stems present. Re-establishment of vegetation has not occurred like the surrounding pasture.

Inspection Photos



Photo 4. Facing south at the east side of the location. This area is the fill slope and is not leveled very well.

Inspection Photos



Photo 5. Facing west toward the location. The location is bare of vegetation.

Inspection Photos



Photo 6. Facing north at the east side of the location. This area is the fill slope and is not leveled very well.

Inspection Photos



Photo 7. Facing north toward the west side of the location. Photo shows green vegetation establishment outside of the location.

Inspection Photos



Photo 8. Facing west outside of the location at the adjacent field (reference area). Vegetation consist of Blue grama, Fringed sage, Western wheat, Prairie threeawn.