

Inspection Photos

API: 05-043-05088

Operator: JAVERNICK OIL

Inspection Date: 4/10/2019

Inspection Photos



Photo 1. Facing north toward the wellhead.

Inspection Photos



Photo 2. Soil has been brought into the erosional channel near the wellhead. It appears more material is need to slope and stabilize the embankment.

Inspection Photos



Photo 3. View of the western project area from the western edge facing southward. Wellhead is adjacent to an erosion channel. This area needs immediate stabilization to prevent any further erosion.

Inspection Photos



Photo 4. Oil stained soil still appears around the wellhead.

Inspection Photos



Photo 5. View of erosional headcut, approximately 3 feet wide and deep, along the access road (Lat/Long:38.33276,-105.11330. Stormwater controls have not been installed.