

Inspection Photos

API: 05-043-06222

Operator: INCREMENTAL OIL & GAS

Inspection Date: 4/10/2019

Inspection Photos



Photo 1. Facing northwest along the reclaimed access road.

Inspection Photos



Photo 3. There is grass germination beginning to occur.

Inspection Photos



Photo 3. Facing north toward the east side of the location This area has been recontoured and reclaimed.

Inspection Photos



Photo 4. Facing northwest toward the location.

Inspection Photos



Photo 5. There is an embankment at the east side of the location that has not been recontoured.

Inspection Photos



Photo 6. Facing north at the east side of the location. There is an embankment at the east side of the location that has not been recontoured. Approximately 8'h x15'w.