

PIT STATUS EVALUATION FORM

Facility ID: 115133

Pit Name: RUNNING CREEK 15-5

☐ Duplicate Record(s) Pit #115066, 111257, 111258
115134, 115135, 115180**Legend**

- Producing or Shut In Well
- ⊕ Temp Aban Well
- ⊕ Abandoned Well
- ⊕ Dry & Aban Well
- Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- Tank Fence

1:6,000

Feet

 Image Source:
 USDA National Agricultural Imagery
 Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: THOMAS OPERATING COMPANY INC

T: 6S R: 64W Sec: 15 QQ: SWNW 6th Meridian

Latitude: 39.529674 Longitude: -104.548618 NAD83

County: Elbert, CO

County Code: 039

Pit Status Evaluation☐ Active☐ Form 15: Pit Permit NA Assoc. Well Seq No(s) 06476☐ Other documentation _____☐ Aerial photo verification _____☒ Closed☐ Form 27: Remediation Workplan _____☐ Form 4: Sundry Notice _____☐ Rule 903a.(2)B☐ Evidence pit(s) existed, no closure docs & well not PR, AC or SI

Well API Seq #(s) _____

☐ Other documentation LIE (1987) "no earthen pits but guess there is a large UST"☐ Abandoned☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs☒ Site Visit☐ No Site Visit☐ Add'l Review☐ UnknownNotes: Common Use with Running Creek 15-3, 15-6, 15-5 battery tank site.FIELD VISIT 6-3-2008: PIT BACKFILLED

Facility ID 115133
Well API 05-039-06476
Well API 05-039-06480
Well API 05-039-06509

Running Creek 15-3, 15-5 & 15-6
Running Creek 15-5
Running Creek 15-3
Running Creek 15-6

June 3, 2008



Photo 1. Lease sign for Running creek 15-3 and former pit site beyond berm



Photo 2. Looking southwest showing recently backfilled pit inside fence