

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

687904545

**FIELD INSPECTION FORM**

Loc ID 333591 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215623	WELL	PR	11/01/2018	GW	067-07228	KNIGHT E 1	PR
276393	WELL	PR		GW	067-09021	KNIGHT E 2	PR
300108	WELL	PR		GW	067-09654	KNIGHT E 3	PR

**General Comment:**

[Conducted on site inspection of location as required. Photos at the end of this inspection report.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road with locked gate.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels and placards on tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Location sign posted at entrance.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact information is posted.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Cattle panels.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and wire		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Flow Line	# 4		corrective date
Comment:	E#2 has 1-3" steel line from wellhead to separator. 2-2" steel manual and level control dump lines form separator to produced water tank. Separator outlet has 4" steel line through meter house and offsite to dogleg.		

Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Wellheads with bradenhead access.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	MCC for electric VFD drive motors on pumpjack.		
Corrective Action:		Date:	
Type: Flow Line	# 7		
Comment:	E#1 and E#2 have 2-3" steel lines from wellhead to seperator. 2-2" steel seperator dump lines to produced water tank. 1-2" Manual line dump to produced water tank. 2-3" steel lines from seperator to meter house and offsite to dogleg.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	PBV STEEL		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215623 Type: WELL API Number: 067-07228 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

Facility ID: 276393 Type: WELL API Number: 067-09021 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

Facility ID: 300108 Type: WELL API Number: 067-09654 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904546	Location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792254">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792254</a>