

Inspection Photos
Location Name: GE# 20-05X
Location ID: 308792



Photo 1 PU and HYD motor skid



Photo 2 Sep/meter house

Inspection Photos
Location Name: GE# 20-05X
Location ID: 308792



Photo 3 Stained soil around HYD skid

Photo 4 Stained soil around HYD skid

Inspection Photos
Location Name: GE# 20-05X
Location ID: 308792



Photo 5 Production pit