

Inspection Photos
Location Name: GE#20-03
Location ID:308859



Photo 1 sep/meter house. Location sign is faded and not legible.



Photo 2 Stained soil under drain line for separator.

Inspection Photos
Location Name: GE#20-03
Location ID:308859



Photo 3 Production pit.



Photo 4 Stained soil around HYD motor skid

Inspection Photos
Location Name: GE#20-03
Location ID:308859



Photo 5 stained soil around HYD motor skid



Photo 6 WH and HYD motor skid

Inspection Photos
Location Name: GE#20-03
Location ID:308859



Photo 7 Unmarked guy line anchor.



Photo 8 unmarked guy line anchor/