

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

690003291

**FIELD INSPECTION FORM**

Loc ID 336588 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250657	WELL	SI	05/01/2017	GW	123-18460	UPRC 9-12J5	SI
297705	WELL	SI	01/01/2019	GW	123-28045	REI H 9-33D	SI
300665	WELL	SI	01/01/2019	OW	123-29814	REI H 9-32D	SI

**General Comment:**

Empty text area for general comments.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Plunger Lift	# 3				
Comment:					
Corrective Action:		Date:			

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	<input style="width: 95%;" type="text"/>		
Other (Content)	<input style="width: 95%;" type="text"/>		
Other (Capacity)	<input style="width: 95%;" type="text"/>		
Other (Type)	<input style="width: 95%;" type="text"/>		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 250657 Type: WELL API Number: 123-18460 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in at flow line connection to the flow line.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 297705 Type: WELL API Number: 123-28045 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in at wellhead connection to flow line.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 300665 Type: WELL API Number: 123-29814 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in at wellhead connection to the flow line.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On Friday, April 12, 2019 at 11:20, I, Craig Carlile conducted an on-site inspection at: 336588 UPRC-63N65W 9SWSW                      Operated by: Anadarco                      While there I observed: Three Well(s) Shut In                      Possible compliance issues observed:                      No: ? Routine Inspection.                      This is a summary of the inspection report.</p>	carlilec	04/12/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003292	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793538">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793538</a>