

Inspection Photos
Location Name: William D. Landsdown #1
Location ID: 317613



Pic 1 1 WH/PU sign faded and in disrepair



Pic 2 Electric panel knocked over

Inspection Photos
Location Name: William D. Landsdown #1
Location ID: 317613



Pic 3



Pic 4 Vert sep building in disrepair, not plugged line.

Inspection Photos
Location Name: William D. Landsdown #1
Location ID: 317613



Pic 5 unused unmarked and not LOTO riser



Pic 6

Inspection Photos
Location Name: William D. Landsdown #1
Location ID: 317613



Pic 7 Gas meter run unused. Unmarked and not LOTO risers

Pic 8

Inspection Photos
Location Name: William D. Landsdown #1
Location ID: 317613



Pic 9 Produced water tank, berms not adequate and in disrepair



Pic 10 unused unmarked and not LOTO rises, and stained soil.

Inspection Photos
Location Name: William D. Landsdown #1
Location ID: 317613



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.11936, -104.7881, 4884.6ft, 295°
04/11/2019 09:37:41

Pic 11 Tank loc sign faded, NFPA placards torn off



COLORADO OIL AND GAS CONSERVATION COMMISSION
40.11936, -104.78794, 4887.4ft, 2°
04/11/2019 09:38:04

Pic 12 Location does not have proper drainage reeling across location

Inspection Photos
Location Name: William D. Landsdown #1
Location ID: 317613



Pic 13. Unused equipment what appears to be casing on location



Pic 14 no bull plug installed in production casing valve.