

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2019

Submitted Date:

04/12/2019

Document Number:

696300111**FIELD INSPECTION FORM**Loc ID 333027 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286096	WELL	TA	04/16/2018	GW	123-24122	GREAT WESTERN 27-51	TA
286653	WELL	TA	04/16/2018	GW	123-24266	GREAT WESTERN 27-32	TA
287295	WELL	TA	04/16/2018	GW	123-24287	GREAT WESTERN 27-41	TA
287299	WELL	TA	04/16/2018	GW	123-24283	GREAT WESTERN 27-31	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	All 4 wellheads 27-31, 32, 42 & 51 have unused equipment, see photos #1, 3, 4, & 5		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019
Type	OTHER		
Comment:	Stained soil around the loadline bucket inside tank berm. See Photos #8, 9 & 10		
Corrective Action:	"Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS"	Date:	05/13/2019
Type	OTHER		
Comment:	Stained Soil around leaking Casing Collar on wells 27-41 and 27-51, See photos #2 & 6		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."	Date:	05/13/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Chainlink		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation Equipment		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	BV FIBERGLASS		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:	Shares a berm with the Crude Oil Tanks									
Corrective Action:								Date:		
Contents		#	Capacity	Type		Tank ID	SE GPS			
CRUDE OIL		3	300 BBLS	STEEL AST			40.460220,-104.874200			
Comment:										
Corrective Action:								Date:		

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 286096 Type: WELL API Number: 123-24122 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 286653 Type: WELL API Number: 123-24266 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287295 Type: WELL API Number: 123-24287 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287299 Type: WELL API Number: 123-24283 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>On 04/09/2019, I Erica Petrie performed an inspection of the Great Western 7 Pad, Wellheads and Tank Battery (Location ID 333027), owned and operated by Great Western Operating Company LLC.</p> <p>Weather Conditions: Clear, dry and sunny.</p> <p>While on inspection I observed the following issue(s):</p> <p>Stained soil from the Loadline bucket, see photo #8, 9 &amp; 10, Cite rule 907.e</p> <p>Unmarked 1" risers on wells 27-31, 32, 41 &amp; 51, see photos #1, 3, 4, &amp; 5, Cite rule 603.f</p> <p>Wellheads 27-31, 32, 41 and 51 have unused wellhead parts, see photos #1, 3, 4, &amp; 5, Cite rule 603.f</p> <p>Stained soil on Wells 27-41 and 27-51 appears to be from the Casing Collar leaking, see photo #2 &amp; 6, Cite rule 907.e</p> <p>Continuing Education Inspection.</p> <p>END.</p>	petrie	04/12/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300116	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793800">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793800</a>

--	--	--