

# Inspection Photos

API: 05-071-06435

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/12/2019

## Inspection Photos



**Photo 1.** Facing toward the access road which has been recontoured and reclaimed.

## Inspection Photos



**Photo 2.** Pipe has been removed from this area. Rock rip/rap has been placed in the drainage for stabilization.

## Inspection Photos



**Photo 3.** Facing toward the access road which has been recontoured and reclaimed.

## Inspection Photos



**Photo 4.** There is numerous Scotch thistle plants emerging in the area of photos 4.