

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

696100756

FIELD INSPECTION FORM

Loc ID 331575 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263571	WELL	SI	01/01/2019	OW	123-20923	NHF 24-9	TA

General Comment:

[This is a WELL Inspection.](#)
[Well: TA](#)
[Battery & ALL Equipment is Shut-down.](#)
[Centralized Battery serves 2 Location IDs \(331573, 331575\). \(1-well:TA, 1-well: TA\).](#)
[Refer to FIR #696100754 and/or Location ID #331573 for Battery / Facility, Equipment info.](#)

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Type	OTHER		
Comment:	Refer to FIR #696100754 and/or Location ID #331573 for additional Fencing info.		
Corrective Action:			Date:

Equipment:				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type:	#			
Comment:	Refer to FIR #696100754 and/or Location ID #331573 for additional Equipment info.			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Bradenhead appears plumbed to surface.			
Corrective Action:				Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:		
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.408457,-104.447118
Comment:	Centralized Battery serves 2 Location IDs (331573, 331575). Refer to FIR #696100754 and/or Location ID #331573 for Tanks & Berms info.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 263571 Type: WELL API Number: 123-20923 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. All production valves shut.
Form 5A #402004479 indicates DH plug set w/ pressure test. TA date: 02/15/2019.
(Approval Pending).
PDC plans to return well to production later.

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary: On FRI APR 12, 2019 at approximately 13:51 hrs. I, Bret Evins, conducted an on-site inspection at: Facility ID #331575, NHF-65N63W /9SESW Operated by PDC Energy. While there I observed: Well(s) TA & Battery shut-down. Routine Inspection.</p> <p>No Corrective Actions observed. This is a summary of the inspection report.</p>	evinsb	04/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100757	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793951