

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2019

Submitted Date:

04/13/2019

Document Number:

696100758**FIELD INSPECTION FORM**Loc ID 331096 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258490	WELL	SI	09/01/2017	GW	123-20147	NAT'L HOG FARM 14-9	PA

General Comment:This is a **PLUGGED & ABANDONED WELL, ABANDONED BATTERY** Inspection.

Well: PA

Battery: Abandoned & most equipment removed except gas meter run & riser.

Abandoned Battery SE corner GPS coordinates: 40.407174, -104.450663

Reclamation progressing.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Gas meter run		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run & riser at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photo #2.		
Corrective Action:	Remove unused gas meter run & riser at Abandoned Battery site. Comply w/ Rule 603.f.		Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 258490 Type: WELL API Number: 123-20147 Status: SI Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: [Appears to have been P&A.](#)
[Form 6 #401954234 indicates plugging date: 01/29/2019. \(Approval Pending\).](#)
[Reclamation progressing.](#)

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary: On FRI APR 12, 2019 at approximately 15:48 hrs. I, Bret Evins, conducted an on-site inspection at: Facility ID #331096, NAT'L HOG FARM-65N63W /9SWSW. Operated by PDC Energy. While there I observed: Well(s) PA. Battery: Abandoned & most equipment removed except gas meter run & riser. Reclamation progressing. 1 - Corrective Actions observed. 1.) Unused gas meter run & riser at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photo #2. Remove unused gas meter run & riser at Abandoned Battery site. Comply w/ Rule 603.f.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/13/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100759	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794069