

Inspection Photos
Location Name: AC#19-16
Location ID: 308967



Photo 1 WH and HYD sound walls



Photo 2 Sep/meter house and 25bbl produced water tank.

Inspection Photos
Location Name: AC#19-16
Location ID: 308967




Photo 3 A pile of what appears to stained soil.

Photo 4 Stained soil around HYD motor skid.

Inspection Photos
Location Name: AC#19-16
Location ID: 308967



Photo 5 Stained soil around HYD motor skid.

Photo 6 Production water pit.