

**Inspection Photos**  
**Location Name: HR#33-06V and HR#33-06-02**  
**Location ID: 333874**



**Photo 1 HR#33-06V and HR#33-06-02 Dual sep/meter house.**

**Photo 2 HR#33-06V WH and HYD motor skids for both wells.**


**Inspection Photos**  
**Location Name: HR#33-06V and HR#33-06-02**  
**Location ID: 333874**



**Photo 3 HR#33-06-02 WH.**

**Photo 4 HR#33-06-02 Mechanical issue packing leaking and being drained through hose onto ground.**

**Inspection Photos**  
**Location Name: HR#33-06V and HR#33-06-02**  
**Location ID: 333874**



**Photo 5 HR#33-06V Stained soil around WH.**

**Photo 6 stained soil around both wells HYD motor skids**

**Inspection Photos**  
**Location Name: HR#33-06V and HR#33-06-02**  
**Location ID: 333874**



**Photo 7 stained soil around both HYD motor skids.**



**Photo 8 stained soil around both wells HYD motor skids**

**Inspection Photos**  
**Location Name: HR#33-06V and HR#33-06-02**  
**Location ID: 333874**



**Photo 9 Produced water pit #1**

**Photo 10 Produced water pit #2**