

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

688401873

FIELD INSPECTION FORM

Loc ID 307751 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256549	WELL	PR	08/28/2002	GW	071-06916	HILL RANCH 32-15R	PR
256550	WELL	PR		GW	071-06917	HILL RANCH 32-15V	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

						corrective date
Type: Deadman # & Marked	# 6					
Comment:						
Corrective Action:				Date:		
Type: Vertical Separator	# 2					
Comment:						
Corrective Action:				Date:		
Type: Pump Jack	# 1					
Comment:						
Corrective Action:				Date:		
Type: Other	#					
Comment:	Braden head appears to be plumbed to surface					
Corrective Action:				Date:		
Type: Prime Mover	# 2					
Comment:	Gas powered HYD motors					
Corrective Action:				Date:		
Type: Gas Meter Run	# 2					
Comment:						
Corrective Action:				Date:		
Type: Progressive Cavity	# 1					

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 256549 Type: WELL API Number: 071-06916 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

Facility ID: 256550 Type: WELL API Number: 071-06917 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Routine inspection	silverr	04/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401874	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794093