

Inspection Photos
Location Name: APACHE CANYON 26-08 V
API #: 05-071-07559
Insp. Doc. # 695100493



PHOTO 1: LOCATION

PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: APACHE CANYON 26-08 V
API #: 05-071-07559
Insp. Doc. # 695100493



PHOTO 3: IMPACTED SOIL FANNING OUT FROM FUEL GAS SCUBBER ON COMPRESSOR OVER TO METER HOUSE APP. 5" AT ITS NARROWEST POINT (NEXT TO SCUBBER ON COMPRESSOR SKID) AND APP. 3.5' AT IS WIDEST POINT (AGAINST THE METERHOUSE). THERE IS ALSO A FILM OF OIL ON THE BOTTOM ¼ OF METERHOUSE WALL.

PHOTO 4: APP. 3' BY 2' AREA OF IMPACTED SOIL ON THE NORTHEAST SIDE OF METER HOUSE.

Inspection Photos

Location Name: APACHE CANYON 26-08 V

API #: 05-071-07559

Insp. Doc. # 695100493



PHOTO 5: TWO UNMARKED 1" RISERS NORTHEAST SIDE OF COMPRESSOR SKID.



PHOTO 6: NO ACHOR MARKER IN PIT.

