

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:			Date:

Equipment:

Type: Plunger Lift	# 1				corrective date
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED E&P		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	OTHER	STEEL AST		
Comment:		Bradenhead monitoring tank at wellhead.			
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)	41 Bbl				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 437340 Type: WELL API Number: 123-39496 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 437343 Type: WELL API Number: 123-39498 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Monday, April 15, 2019 at 12:44, I, Craig Carlile conducted an on-site inspection at: 329103 CRUICKSHANK 1C-24HZ Operated by: Anadarco While there I observed: Two HZ Wells, One with Bradenhead monitoring tank, Possible compliance issues observed: No: ? Routine Inspection. Yes: ? During this inspection the following possible compliance issues were observed: Choose an item. Choose an item. This is a summary of the inspection report.</p>	carlilec	04/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003326	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795362