

SG 34-28
Api. # 05-045-15816
Inspection # 689703038



SG 34-28
Api. # 05-045-15816
Inspection # 689703038



04.15.2019 10:21

SG 34-28
Api. # 05-045-15816
Inspection # 689703038



Unused cable on edge of location.

SG 34-28
Api. # 05-045-15816
Inspection # 689703038



Holes in ditch going into ditch.

SG 34-28
Api. # 05-045-15816
Inspection # 689703038



Storm water channel in check dam behind tank battery.

SG 34-28
Api. # 05-045-15816
Inspection # 689703038



Erosion of location in drainage into check dam.

SG 34-28
Api. # 05-045-15816
Inspection # 689703038



Washing of ditch from check dam.