

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-05157**  
**Date: 4-9-2019**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of erosional channeling and sediment discharge within the eastern project area, facing eastward toward the surrounding cultivated field.



Photo 5. View of wattles no longer functioning within the eastern project area. This stormwater control is not sufficient to manage erosion within this area.



Photo 6. View of erosional scouring from stormwater flows that appear to have breached the access road and are eroding down slope.