

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2019

Submitted Date:

04/10/2019

Document Number:

693900138

FIELD INSPECTION FORM

Loc ID 333828 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
,		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216107	WELL	PR	01/20/1992	GW	067-07713	KRAJACK 43-27 1	RI
294380	WELL	PR	01/12/2016	GW	067-09483	KRAJACK 43-27 3	RI
294381	WELL	PR	01/14/2008	GW	067-09484	KRAJACK 43-27 4	RI

General Comment:

[This is an interim reclamation and stormwater inspection.](#)

Inspected Facilities

Facility ID: 216107 Type: WELL API Number: 067-07713 Status: PR Insp. Status: RI

Facility ID: 294380 Type: WELL API Number: 067-09483 Status: PR Insp. Status: RI

Facility ID: 294381 Type: WELL API Number: 067-09484 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by pinyon juniper woodland and adjacent to an irrigation ditch along the southern edge. Revegetation is progressing within portions of the reclamation areas, although sparse on the well pad cut-slope. This needs to be monitored during the 2019 growing season, and stabilization measures installed if revegetation is not increasing.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action Date _____

1003a. Waste and Debris removed? Pass

Comment

Corrective Action Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action Date _____

Guy line anchors marked? _____

Comment

Corrective Action Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosional rilling is occurring within the southern project area. The eastern diversion is downcutting and carrying sediment offsite. Cobble rundown in southwestern project area appears to be functioning.

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the southern and eastern project area. Also, see comments above regarding stabilization of the well pad cut slope.

Date: 05/10/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402002570	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789980
693900139	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789979