

# Inspection Photos

API: 05-043-06216

Operator: AUSCO PETROLEUM INC

Inspection Date: 4/10/2019

## Inspection Photos



**Photo 1.** View of the northeastern project area from the access road facing eastward. This area has been seeded and hydro-mulched.

## Inspection Photos



**Photo 2.** Guyline anchors have been marked, however markers should be not less than 4ft. In height.

## Inspection Photos



**Photo 3.** Erosion channel has not been repaired at the east side of the location.

## Inspection Photos



**Photo 4.** View of the southern project area from the southeastern corner facing westward. Unused equipment is stored along the outer edges of the well pad.

## Inspection Photos



**Photo 5.** View of the project area from the southeastern corner facing center.