

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2019

Submitted Date:

04/17/2019

Document Number:

696100788

FIELD INSPECTION FORM

Loc ID 322586 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------------------------------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 243897 | WELL | PA | 12/05/2018 | OW | 123-11689 | HERGERT 1-6 | PA |

General Comment:

This is a **PLUGGED & ABANDONED WELL** Inspection.
Abandoned wellsite appears reclaimed.
Battery is Abandoned & ALL equipment has NOW been removed.
Reclamation progressing.
Abandoned Battery SE Corner GPS coordinates: 40.509341, -104.820923.

Location

| | | | |
|--------------------|----------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |

Overall Good:

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--|--|-------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | <p>From prior FIR: Unused gas meter run & automation tower at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. See photo #1. This FIR: Unused gas meter run & automation tower at Abandoned Battery site NOW removed. See photo #2.</p> | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|--|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No Comment: _____ <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|--|--|-------|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|--|-------|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 243897 Type: WELL API Number: 123-11689 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to have been P&A.
ALL equipment appears removed & wellsite appears reclaimed.
Form 6 #401892436 indicates plugging date: 12/05/2018. (Approved).

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary: On WED APR 17, 2019 at approximately 11:03 hrs. I, Bret Evins, conducted an on-site inspection at: Location ID #322586, HERGERT-66N66W /6SWSE. Operated by: PDC Energy. While there I observed: Well(s) Plugged & Abandoned. Battery Abandoned & ALL equipment NOW removed. Follow-up to FIR #696100405 dated 03/07/2019. 1 of 1 - Corrective Actions addressed. 1.) Unused gas meter run & automation tower at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. Unused gas meter run & automation tower at Abandoned Battery site NOW removed. See photos #1, 2. Reclamation progressing.</p> <p>No Corrective Actions observed on this FIR. This is a summary of the inspection report.</p> | evinsb | 04/17/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696100789 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4798860 |