

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2019

Submitted Date:

04/17/2019

Document Number:

688800499

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
313472 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224176	WELL	IJ	01/31/2008	DSPW	083-06240	MCELMO DOME UNIT 9-38-18 (EPA) HWD-1	EI
450887	TANK BATTERY	AC	05/31/2017		-	Hovenweep HWD-1 Tank Battery	EI

General Comment:

On April 16, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan McElmo Dome Unit 9-38-18 HWD-1. For the most recent field inspection report of this facility, please refer to document #685304894. This field inspection was in response to Spill/Release Point ID #463712. An RW Trucking water hauler was on site during this field inspection.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	ASTs have labels and placards.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign posted near location entrance.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Operator contact information posted on location signs.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Perimeter fencing with cattle guard at entrance.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Fiberglass building housing injection equipment		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLS	STEEL AST		37.559962,-108.829936

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 224176 Type: WELL API Number: 083-06240 Status: IJ Insp. Status: EI

Facility ID: 450887 Type: TANK API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical container.
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On April 16, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan McElmo Dome Unit 9-38-18 HWD-1. For the most recent field inspection report of this facility, please refer to document #685304894. This field inspection was in response to Spill/Release Point ID #463712. An RW Trucking water hauler was on site during this field inspection.	hughesjo	04/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800500	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4799434