

Maralex Resources Inc.

Api # 05-077-08423

Inspection # 675002188



Photo of location from entrance

Maralex Resources Inc.
Api # 05-077-08423
Inspection # 675002188



Photo of location from entrance

Maralex Resources Inc.
Api # 05-077-08423
Inspection # 675002188



Tank Battery



Well head

Maralex Resources Inc.
Api # 05-077-08423
Inspection # 675002188



Erosion moving sediment off location



Erosion moving sediment off location

Maralex Resources Inc.
Api # 05-077-08423
Inspection # 675002188



Trash on location



Trash on location

Maralex Resources Inc.
Api # 05-077-08423
Inspection # 675002188



Unused equipment on location



Storm water erosion moving across access entrance.

Maralex Resources Inc.
Api # 05-077-08423
Inspection # 675002188



Pit on location.